

# 2020 Mid-Atlantic Quality Assurance Workshop



## Causes and Prevention of Weld Cracking

by




Duane K. Miller, P.E., Sc.D



# Causes and Prevention of Weld Cracking

## and Tearing

in bridge welding applications




# Causes and Prevention of Weld Cracking

If you have a weld cracking problem...

....the first question to ask is this: “When did the cracking occur?”

## Possible answers


- 
- During fabrication
  - In service
  - I don't know

# Causes and Prevention of Weld Cracking

If you have a weld cracking problem...


....the second question to ask is this: “Where is the crack located?”

## Possible answers

- 
- In the weld
  - Next to the weld
  - I don't know

# Causes and Prevention of Weld Cracking and Tearing

## in bridge welding applications





- New construction: A709 steels
- New construction: Unlisted steels
- Existing inventory: Historic, obsolete steels


# Causes and Prevention of Weld Cracking

## OUTLINE


- Introduction
- Centerline cracks
- Underbead cracks
- Transverse cracks
- Lamellar tearing
- Preheat
- Postheat




# Centerline Cracking




# Underbead Cracking




# Transverse Cracking



# Lamellar Tearing




# Centerline Cracking




# Centerline Cracking


## Characteristics

- Near the center of a weld bead
- Is present as weld cools—is not delayed
- Occurs at high temperatures—the crack surface may exhibit “temper colors”
- Cracks may extend from one weld layer into the next, but are more commonly isolated to one layer
- Overloaded fillet welds often fail through the weld throat and may look like centerline cracks





# Centerline Cracking





Centerline cracks are near the weld bead centerline;  
may not be in the center of the joint.

# Centerline Cracking



## Cause 1: Segregation Cracking

Low melting point ingredients segregate to the center during solidification









# Centerline Cracking





# Centerline Cracking





# Centerline Cracking



# Centerline Cracking




# Centerline Cracking



# Centerline Cracking

## Cause 1: Segregation Cracking

Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
  - Low levels of
    - Phosphorous (P)
    - Sulfur (S)
    - Zinc (Zn)
    - Tin (Sn)
    - Copper (Cu)
    - Carbon (C)

# Centerline Cracking

## Cause 1: Segregation Cracking



## TWI Hot Cracking Susceptibility (Unit of Crack Susceptibility)

$$\text{UCS} = 230 \text{ C} + 190 \text{ S} + 75 \text{ P} + 45 \text{ Nb} - 12.3 \text{ Si} - 5.4 \text{ Mn} - 1$$

$\text{UCS} \leq 10$  “High Resistance to Cracking”


$\text{UCS} > 30$  “Strong Susceptibility to Cracking”

Based on WELD METAL Composition

# Centerline Cracking

## Cause 1: Segregation Cracking

Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
- Minimize admixture

FCAW-g

← 1/4" →


[6 mm]



FCAW-g

← 1/4" →


[6 mm]



# Centerline Cracking

## Cause 1: Segregation Cracking


Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
- Minimize admixture
  - Change joint detail


# ADMIXTURE: High




# ADMIXTURE: High



# ADMIXTURE: Medium




# ADMIXTURE: Medium



# Centerline Cracking

## Cause 1: Segregation Cracking

Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
- Minimize admixture
  - Change joint detail
  - Minimize penetration (unless needed for joint strength)

# ADMIXTURE

Acceptable fillet welds per AASHTO/AWS D1.5




**Minimal Admixture**

**Significant Admixture**

# Centerline Cracking

## Cause 1: Segregation Cracking


Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
- Minimize admixture
  - Change joint detail
  - Minimize penetration (unless needed for joint strength)
  - Use “buttering” (overlay) technique

# BUTTERING




# BUTTERING



# Centerline Cracking

## Cause 1: Segregation Cracking


Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
- Minimize admixture
- For sulfur, use higher manganese (Mn) filler metal

Sulfur is not present as an element, but as a compound; either FeS or MnS.






# Centerline Cracking

## Cause 1: Segregation Cracking

Low melting point ingredients segregate to the center during solidification




**Solution: Minimize low melting point ingredients in the molten weld metal**

- Use “good” steel
- Minimize admixture
- **For sulfur, use higher manganese (Mn) filler metal**


# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking

The cross-sectional width of the bead is less than the depth of the bead





**Solution: Make sure each bead is wider than it is deep**



# Centerline Cracking

**W** is the width of the weld bead  
**D** is the depth of the weld bead




When **W** < **D**, the weld tends to crack



# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking



The cross-sectional width of the bead is less than the depth of the bead





# Centerline Cracking





# Centerline Cracking





# Centerline Cracking





# Centerline Cracking



# Centerline Cracking








# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking



The cross-sectional width of the bead is less than the depth of the bead

**Solution: Make sure each bead is wider than it is deep**

Width-to-Depth Ratio (W/D) should be:

**1:1 minimum**


**1.2: 1 preferred**

**1.4:1 is ideal**

# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking

The cross-sectional width of the bead is less than the depth of the bead




**Solution: Make sure each bead is wider than it is deep**

- Use a proper joint detail

# AASHTO/AWS D1.5:2015 Bridge Welding Code




Single-bevel-groove weld (4)  
 Butt joint (B)  
 T-joint (T)  
 Corner joint (C)




Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Weld Size (E)	Notes
		T <sub>1</sub>	T <sub>2</sub>	Root Opening Root Face Groove Angle	Tolerances				
					As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)			
SMAW	BTC-P4	U	U	R = 0 f = 1/8 min. α = 45°	+1/16, -0 +U -0 +10°, -0°	+1/8, -1/16 ±1/16 +10°, -5°	All	S-1/8	b, e, f, g, j, k
GMAW FCAW	BTC-P4-GF	1/4 min.	U	R = 0 f = 1/8 min. α = 45°	+1/16, -0 +U -0 +10°, -0°	+1/8, -1/16 ±1/16 +10°, -5°	F, H V, OH	S S-1/8	a, b, f, g, j, k
SAW	TC-P4-S	7/16 min.	U	R = 0 f = 1/4 min. α = 60°	±0 +U, -0 +10°, -0°	+1/16, -0 ±1/16 +10°, -5°	F	S	b, f, g, j, k


# AASHTO/AWS D1.5:2015 Bridge Welding Code




Welding Process	Root Opening Root Face Groove Angle
SMAW	$R = 0$ $f = 1/8''$ min. $\alpha = 45^\circ$
GMAW FCAW	$R = 0$ $f = 1/8''$ min. $\alpha = 45^\circ$
SAW	$R = 0$ $f = 1/4''$ min. $\alpha = 60^\circ$






BTC-P4, BTC-P4-GF




TC-P4-S



# AASHTO/AWS D1.5:2015 Bridge Welding Code




**TC-U4**



30°

# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking




The cross-sectional width of the bead is less than the depth of the bead

**Solution: Make sure each bead is wider than it is deep**


- Use a proper joint detail
- Control current density ( $\delta$ )

# CURRENT DENSITY ( $\delta$ )

$I =$  current



$d =$  diameter



$$\delta = \left( \frac{I}{A} \right) \propto \left( \frac{I}{d^2} \right)$$

where


$I =$  current (amps)

$A =$  cross sectional area of filler metal

$d =$  diameter of filler metal

# PENETRATION


Acceptable fillet welds per AISC, AWS D1.1




**Normal Current Density**

**Excessive Current Density**

# FILLET WELDS IN SKEWED TEE JOINTS




**In 90° joint,  $W/D = 2:1$**



**In 45° joint, acute side is problematic**

# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking




The cross-sectional width of the bead is less than the depth of the bead

**Solution: Make sure each bead is wider than it is deep**

- Use a proper joint detail
- Control current density ( $\delta$ )

# Centerline Cracking

## Cause 2: Width-to-Depth Ratio Cracking




The cross-sectional width of the bead is less than the depth of the bead

**Solution: Make sure each bead is wider than it is deep**

**A special type of cracking in bridge applications:**

**“opposed arc cracking”**





**OGDEN**  
WELDING SYSTEMS


NA-3W  
AMPERES DC  
VOLTS DC


NA-3W  
AMPERES DC  
VOLTS DC


10.00000  
DIRECTION OFF  
TRAVEL MODE  
PANEL POWER  
ARC RECOVERY  
WELD START  
WELD STOP
















































**HPS70W Stiffener**



# Opposed Arc Cracking

**Cause: Bridging of puddle across tee joint**


**Solution: Eliminate the bridging**

- Use thicker stiffeners ( $> 3/8$  [10 mm])
- Cascade the arcs so they are not opposed
- Adjust welding current and current density
- Adjust torch angle and electrode placement



# Centerline Cracking

## Cause 3: Surface Profile Cracking



The surface of the weld is concave





# Centerline Cracking





# Centerline Cracking





Any concave pass, especially root passes




















# Centerline Cracking

## Cause 3: Surface Profile Cracking

The surface of the weld is concave




## Solution: Make sure the bead surface is convex

- Use a proper welding procedure
  - Shielding gas
    - Argon/oxygen combinations tend to give concave beads
    - Argon/CO<sub>2</sub> combinations tend to give flatter/more convex beads
    - Vertical up (convex) versus vertical down (concave)
    - Lower voltage, amperage (“colder”)

# Centerline Cracking

## Cause 3: Surface Profile Cracking


The surface of the weld is concave



**Solution: Make sure the bead surface is convex**

- Use a proper welding procedure

# Centerline Cracking




# Centerline Cracking

**Cause 1: Segregation Cracking**

**Cause 2: Width-to-Depth Ratio Cracking**


**Cause 3: Surface Profile Cracking**




**To troubleshoot, use a countdown.**

- Surface profile: is it concave?
- If not, check the cross section: is the bead deeper than it is wide?
- If not, check the weld deposit chemistry.


# HOT CRACK



Centerline




Underbead





Transverse

# COLD CRACKS


# Underbead Cracking





# Underbead Cracking



## Characteristics




- Located at weld toe or in heat affected zone (HAZ)
- Occurs at lower temperatures
- May be delayed—occurring up to 72 hours (or more) after welding
- May occur immediately after the weldment cools sufficiently
- Is driven by the transverse shrinkage stress
- Can be confused with in-service fatigue cracks which often occur at weld toes

# Underbead Cracking

**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**




# Development of atomic hydrogen




# Migration of atomic hydrogen

Hydrogen




# Migration of atomic hydrogen

Hydrogen



# Shrinkage Stresses


Stress





# Sensitive Material

Sensitive  
Material

**Heat Affected Zone**




# Combining all three....



**Because it takes time for hydrogen to diffuse, and because this cracking only occurs when the steel is cool (< 400°F), it may be “delayed”.**


# Underbead Cracking

**Cause: Excessive hydrogen AND a sensitive material AND an applied or residual stress**




**Solution:**

- Reduce Hydrogen
  - Selection of filler metals
  - Storage and exposure of filler metals
  - Control base metal cleanliness
  - Maximize diffusion of hydrogen




# Underbead Cracking

**Cause: Excessive hydrogen AND a sensitive material AND an applied or residual stress**




## **Solution:**

- Maximize diffusion of hydrogen
  - Increased preheat
  - Increased interpass temperature
  - Higher heat input
  - Thinner weld layers
  - Increased time between passes
  - Slower cooling after welding
  - Post heat




# Underbead Cracking

**Cause: Excessive hydrogen AND a sensitive material AND an applied or residual stress**




## **Solution:**

- Reduce Residual Stress
  - Use matching or undermatching filler metal
  - Control welding sequence
  - Maintain proper preheat and interpass temperatures
  - Peen weld beads




# Underbead Cracking

**Cause: Excessive hydrogen AND a sensitive material AND an applied or residual stress**





## **Solution:**

- Reduce Material (HAZ) Sensitivity
  - Selection of base metal (low hardenability—low carbon, low alloys)
  - Increased preheat
  - Higher heat input
  - Increased interpass temperature





# Underbead Cracking

**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**



# Underbead Cracking



**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**




Typically, when an underbead cracking problem is encountered, all three variables are reduced.

# Underbead Cracking

**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**



Crack-free welding is possible, even with very high hydrogen levels, if the other factors are small.




**Table 4.3**  
**Minimum Preheat and Interpass Temperature, °C [°F]**

Welding Process (Base Metal)	Thickness of Thickest Part at Point of Welding, mm [in]			
	To 20 mm [3/4 in] Incl.	Over 20 mm [3/4 in] to 40 mm [1-1/2 in] Incl.	Over 40 mm [1-1/2 in] to 65 mm [2-1/2 in] Incl.	Over 65 mm [2-1/2 in]
SAW; GMAW; FCAW; SMAW (M 270M/M 270 (A709/A709M) Gr. 250 [36], 345 [50], 345S [50S], 345W [50W], HPS 345W [HPS 50W])	10 [50]	20 [70]	65 [150]	110 [225]
SAW; GMAW; FCAW; SMAW (M 270M/M 270 (A709/A709M) Gr. HPS 485W [HPS 70W] and HPS 690W [HPS 100W])	10 [50]	50 [125]	80 [175]	110 [225]

<sup>a</sup> See 4.2.2 for maximum preheat and interpass temperature limitations.

Note: See Annex G and Tables 12.3, 12.4, and 12.5 for alternate preheat and interpass temperatures.




**Table 12.4**  
**M 270M/M 270 (A709/A709M) Gr. 345W [50W], HPS 345W [HPS 50W], HPS 485W**  
**[HPS 70W] Minimum Preheat and Interpass Temperatures, °C [°F] (see 12.14)**

Thickness t, mm [in]	Heat Input (as calculated by 5.12) kJ/mm [kJ/in]								
	1.2 [30] < HI ≤ 2.0 [50]			2.0 [50] < HI ≤ 2.8 [70]			HI > 2.8 [70]		
	H4	H8	H16	H4	H8	H16	H4	H8	H16
t ≤ 20 [3/4]	40 [125]	60 [150]	80 [200]	40 [100]	40 [100]	60 [150]	40 [100]	40 [100]	40 [100]
20 [3/4] < t ≤ 40 [1-1/2]	100 [200]	100 [250]	120 [275]	80 [175]	100 [200]	120 [250]	60 [150]	80 [175]	100 [200]
40 [1-1/2] < t ≤ 60 [2-1/2]	140 [300]	160 [325]	180 [350]	140 [275]	140 [300]	160 [325]	120 [250]	140 [275]	160 [300]
t > 60 [2-1/2]	180 [350]	180 [350]	200 [375]	160 [325]	180 [350]	200 [350]	140 [300]	160 [325]	180 [350]

Note: H4, H8, and H16 are electrode optional supplemental designators for diffusible hydrogen.

# AWS D1.1:2015 Structural Welding Code—Steel


## Table 5.7 Minimum Fillet Weld Sizes



<b>Base-Metal Thickness (T)<sup>a</sup></b> in. [mm]	<b>Minimum Size of Fillet Weld<sup>b</sup></b> in. [mm]
$T \leq 1/4$ [6]	1/8 [3]
$1/4$ [6] < $T \leq 1/2$ [12]	3/16 [5]
$1/2$ [12] < $T \leq 3/4$ [20]	1/4 [6]
$3/4$ [20] < $T$	5/16 [8]


# AWS D1.1:2015 Structural Welding Code—Steel

## Table 5.7 Minimum Fillet Weld Sizes




<b>Base-Metal Thickness (T)<sup>a</sup></b> <b>in. [mm]</b>	<b>Minimum Size of Fillet Weld<sup>b</sup></b> <b>in. [mm]</b>	<b>Approximate Minimum Heat Input, kJ/in.</b> <b>[kJ/mm]</b>
$T \leq 1/4$ [6]	$1/8$ [3]	7 [0.3]
$1/4$ [6] < $T \leq 1/2$ [12]	$3/16$ [5]	16 [0.6]
$1/2$ [12] < $T \leq 3/4$ [20]	$1/4$ [6]	30 [1.2]
$3/4$ [20] < $T$	$5/16$ [8]	43 [1.7]

# AWS D1.1:2010 Structural Welding Code--Steel




<sup>a</sup>For non-low hydrogen processes.... $T$  equals the thickness of the thicker part joined....For low-hydrogen processes... $T$  equals the thickness of the thinner part....


# HOT CRACK



Centerline




Underbead



Transverse

# COLD CRACKS



# Transverse Cracking






# Transverse Cracking

**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**



# Transverse Cracking


## Characteristics



- May be delayed, just like underbead cracking
- Is caused by longitudinal shrinkage stress (underbead cracking is driven by transverse stress)
- Longitudinal spacing may be very regular
- Must have a sufficiently long weld (typically > 18" long)
- Commonly occurs when welding on higher strength steels that require no preheat (based on the base metal composition)
- Some hardsurfacing deposits are designed to cross crack, thus relieving residual stresses and preventing spalling


# Transverse Cracking

**Cause: Excessive hydrogen AND an applied or residual AND a sensitive material**




**Solution:**

- Reduce Hydrogen
  - Selection of filler metals
  - Storage and exposure of filler metals
  - Control base metal cleanliness
  - Maximize diffusion of hydrogen




# Transverse Cracking

**Cause: Excessive hydrogen AND an applied or residual AND a sensitive material**



**Solution:**


- Reduce Residual Stress
  - Use **matching** or undermatching filler metal
  - Maintain proper preheat and interpass temperatures



**Transverse cracking nearly always involves weld deposits that are higher in strength than the base metal.**


# Transverse Cracking

**Cause: Excessive hydrogen AND an applied or residual AND a sensitive material**





## **Solution:**

- Reduce Material (Weld Metal) Sensitivity
  - Selection of filler metal
  - Use undermatching where possible
  - Increased preheat
  - Higher heat input
  - Increased interpass temperature
  - Control admixture (pickup)





# Transverse Cracking

**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**





# Transverse Cracking


**Cause: Excessive hydrogen AND  
an applied or residual AND  
a sensitive material**



# Lamellar Tearing











# Lamellar Tearing

**Cause: Through thickness weld shrinkage strains cause planar inclusions to join together (tear)**



# Lamellar Tearing


## Characteristics




- Typically occurs immediately outside the heat affected zone
- Typically is not delayed
- Is aggravated by hydrogen (but not caused by hydrogen)
- Occurs less frequently today (2012) than it did in the past (due to improved steel making practices)
- Typically associated with steel thicknesses  $>3/4$ "
- Not to be confused with de-lamination, which typically occurs at the mid-thickness

# Lamellar Tearing

Inclusions, typically  
manganese sulfides




# Lamellar Tearing




# Lamellar Tearing

Step 1: Separation of the inclusions from the surrounding steel




# Lamellar Tearing

Step 2: Ductile tearing of the ligaments between the inclusions



# Lamellar Tearing

**Cause:** Through thickness weld shrinkage strains cause planar inclusions to join together (tear)





## **Solution:**

- Use appropriate joint configurations


# Lamellar Tearing

## Non-preferred Details




# Lamellar Tearing

## Preferred Details




Fillets instead of CJP




CJP with bevel on the problematic side

# Lamellar Tearing

## Preferred Details




PJP instead of CJP




A corner-like tee joint

# Lamellar Tearing

## Buttering Solution




Sensitive Detail



Buttered Detail

# Lamellar Tearing

**Cause:** Through thickness weld shrinkage strains cause planar inclusions to join together (tear)




## **Solution: Better Material**

- Reduce inclusions in the steel
- Control the inclusion shape in the steel

# Lamellar Tearing

**Cause: Through thickness weld shrinkage strains cause planar inclusions to join together (tear)**




## **Solution: Better Detailing**

- Bevel the sensitive member
- Minimize weld volumes: PJP's vs. CJP's
- Minimize weld volumes: Optimized details
- Butter the joint

# Lamellar Tearing

**Cause: Through thickness weld shrinkage strains cause planar inclusions to join together (tear)**




## **Solution: Better Fabrication**

- Minimize shrinkage strains (peening can be helpful when properly done)
- Increased preheat, lower hydrogen
- Weld only once (plan the work)

# Lamellar Tearing


**Cause: Through thickness weld shrinkage strains cause planar inclusions to join together (tear)**



## **Solutions:**

- Better Material
- Better Detailing
- Better Fabrication

# PREHEAT




## **preheat temperature**

The temperature of the base metal in the volume surrounding the point of welding immediately before welding is started. In a multiple pass weld, it is also the temperature immediately before the second and subsequent passes are started.



## **interpass temperature**

In a multipass weld, the temperature of the weld area between weld passes.




**Table 12.5**  
**M 270M/M 270 (A709/A709M) Grade HPS 690W [HPS 100W]**  
**Minimum and Maximum Preheat/Interpass Temperature, °C [°F] (see 12.14)**

Heat Input (as calculated by 5.12) kJ/mm [kJ/in]

Thickness t, mm [in]	Heat Input (as calculated by 5.12) kJ/mm [kJ/in]				
	1.2 [30] ≤ HI < 1.6 [40]	1.6 [40] ≤ HI < 2.0 [50]	2.0 [50] ≤ HI < 2.8 [70]	2.8 [70] ≤ HI < 3.6 [90]	3.6 [90] ≤ HI
6 [1/4] ≤ t ≤ 10 [3/8]	40–60 [100–150]	—	—	—	—
10 [3/8] < t ≤ 13 [1/2]	60–160 [150–300]	40–100 [100–200]	—	—	—
13 [1/2] < t ≤ 20 [3/4]	120–200 [250–400]	100–180 [200–350]	40–120 [100–250]	—	—
20 [3/4] < t ≤ 25 [1]	—	120–200 [250–400]	120–200 [250–400]	60–160 [150–300]	—
25 [1] < t ≤ 50 [2]	—	—	120–200 [250–400]	120–200 [250–400]	100–180 [200–350]
t > 50 [2]	—	—	150–240 [300–450]	140–240 [300–450]	140–240 [300–450]


Note: The table applies to electrodes with the H4 or H8 optional supplemental designator for diffusible hydrogen limits.

# HOT CRACK




Centerline

Preheat to solve cold cracking problems



Underbead




Transverse

# COLD CRACKS

# Postheat

- Heating weldments to 400-450°F immediately after welding
- Holding at elevated temperatures for an hour per inch of thickness of weld deposit
- Significantly reduces diffusible hydrogen levels
- Effective for “cold cracking” problems

# Postheat




**Apply post heat before cold cracking can occur (i.e., before the steel cools to below 400°F).**



## **Wrapping weldments in insulating blankets— essentially the same concept as post heat**


- Caveat 1: wrapping slows cooling rate, but weldment cools from interpass temperature which is often less than 400°F at time weldment is wrapped.
- Caveat 2: wrapping works best when the whole weldment is at elevated temperatures

# Wrapping




# Wrapping





## 12.15.1.1 Minimum Temperature Prior to Hydrogen Diffusion Postheat

When hydrogen diffusion postheat is required, the weld shall not be allowed to cool below the minimum postheat and interpass temperature before being raised to the postheat temperature.





## 12.15.1.2 Hydrogen Diffusion Postheat Temperature Limitations.

When hydrogen diffusion postheat is required, welds and adjacent base metal shall be heated to a temperature of 230°C [450°F] minimum to 315°C [600°F] maximum for not less than one hour for each 25 mm [1 in.] of weld thickness, or two hours, whichever is less. The minimum heating time for repair welds shall be one hour for each 25 mm [1 in.] of repair weld depth from the surface, but not less than one hour. Longer heating periods maybe used.

# Causes and Prevention of Weld Cracking

## OUTLINE

- Introduction
- Centerline cracks
- Underbead cracks
- Transverse cracks
- Lamellar tearing
- Preheat
- Postheat



# 2020 Mid-Atlantic Quality Assurance Workshop



## Causes and Prevention of Weld Cracking


by


Duane K. Miller, P.E., Sc.D



# JOHN'S PASS REPLACEMENT BRIDGE





A large moving bridge with four tall, angled towers over water. The towers are made of steel and have a lattice-like structure. The bridge is in the process of moving, with the towers tilted at an angle. The water is a dark greenish-blue, and the sky is a clear, light blue.

**IS A MOVING BRIDGE A BRIDGE?  
OR A MACHINE?**

**SHOULD THE MOVING PARTS BE  
MANUFACTURED BY A STEEL FABRICATOR?  
OR A MACHINING COMPANY?**







Ellwood City Forge  
Ellwood City, PA

Sold To:

Date: 05/15/07  
P.O.#: 49034  
Job #: F3067

Grade and Description: 4140 Block

Specification: ASTM A668 Class J Rev 04  
Drawing #: 15-1/4" x 8-3/4" x 60" LG.

Job #	Piece #	Heat/ Ingot #	Ingot Size	Ingot Weight	Product Size	Shipped Weight
F3067	09	R8242-2			8-3/4 X 15-1/4 X 60-1/4	
	10	R8242-2			8-3/4 X 15-1/4 X 190-1/8	

**CHEMICAL ANALYSIS**

Heat #	C	Mn	P	S	Si	Ni	Cr	Mo	Al	V	Cu	Hppm	Ti
R8242	.43	.89	.015	.025	.22	.12	.99	.22	.019	.050	.17	1.3	.0032

**TENSILE TEST RESULTS: TENSILE TEST DIA. .505"**

**BRINELL RESULTS**

TENSILE TESTS TAKEN FROM PC 08

Piece #	Test Loc	Yield Strength .2% offset	Tensile Strength	Elong in 2"	R A %	BRINELL
08		84,573	113,196	18	49	236-240-244-245
		83,946	110,613	19	49	

**IMPACT RESULTS: TEST SIZE: 10mm x 10mm**

Piece#	Test Loc	Test Temp	Ft lbs.	%Shear	Lateral Expansion

HEAT TREATMENT OF PC 08 HEAT TREATED IN FURNACES CERTIFIED TO AMS -H-6875  
HEAT TO 1575 DEG F 4 HRS MIN POLY QUENCH, TEMPER 1225 DEG F 9 HRS  
SONIC TESTED P ASTM A 388 - REVEALED NO INDICATIONS

Signed: \_\_\_\_\_

*Kathy Lasele*

Certification Clerk



Ellwood City Forge  
Ellwood City, PA

Ellwood City Forge

4140

Sold To:

Date: 05/15/07  
P.O.#: 49034  
Job #: F3067

Grade and Description:

4140 Block

Specification: ASTM A668 Class J Rev 04  
Drawing #: 15-1/4" x 8-3/4" x 60" LG.

ASTM A668 Class J  
(a forging)

Job #	Piece #	Heat/ Ingot #	Ingot Size	Ingot Weight	Product Size	Shipped Weight
F3067	09	R8242-2			8-3/4 X 15-1/4 X 60-1/4	
	10	R8242-2			8-3/4 X 15-1/4 X 190-1/8	

CHEMICAL ANALYSIS

Heat #	C	Mn	P	S	Si	Ni	Cr	Mo	Al	V	Cu	Hppm	TI
R8242	.43	.89	.015	.025	.22	.12	.99	.22	.019	.050	.17	1.3	.0032

TENSILE TEST RESULTS: TENSILE TEST DIA. .505"

BRINELL RESULTS

TENSILE TESTS TAKEN FROM PC 08

Piece #	Test Loc	Yield Strength .2% offset	Tensile Strength	Elong in 2"	R A %	BRINELL
08		84,573	113,196	18	49	236-240-244-245
		83,946	110,613	19	49	

IMPACT RESULTS: TEST SIZE: 10mm x 10mm

Piece#	Test Loc	Test Temp	Ft lbs.	%Shear	Lateral Expansion

HEAT TREATMENT OF PC 08 HEAT TREATED IN FURNACES CERTIFIED TO AMS -H-6875  
HEAT TO 1575 DEG F 4 HRS MIN POLY QUENCH, TEMPER 1225 DEG F 9 HRS  
SONIC TESTED P ASTM A 388 - REVEALED NO INDICATIONS

C 0.43  
Mn 0.89  
P 0.015  
S 0.025  
Ni 0.12  
Cr 0.99  
Mo 0.22

Yield 84  
Tensile 110

Signed: \_\_\_\_\_

*Kathy Lasele*

Certification Clerk

# AWS A3.0 Standard Welding Terms and Definitions



**Weldability:** The capacity of a material to be welded under the imposed fabrication conditions into a specific, suitably designed structure, and to perform satisfactorily in the intended service.

**Weldability:** A term that usually refers to the relative ease with which a metal can be welded using conventional practice.

# AWS A3.0 Standard Welding Terms and Definitions



**Weldability:** The capacity of a material to be welded under the imposed fabrication conditions into a specific, suitably designed structure, and to perform satisfactorily in the intended service.

**WELDABILITY DOES NOT MEAN “ABLE TO BE WELDED” BUT IS A RELATIVE TERM TO DESCRIBE HOW EASY OR DIFFICULT IT WILL BE TO SUCCESSFULLY WELD THE MATERIAL.**

**ANALOGOUS TO “READABILITY”**

4140

- A weldable material
- Poor weldability



Ellwood City Forge  
Ellwood City, PA

Sold To: JC Industrial Mfg. Corp.  
5700 N.W., 32 CT  
Miami, FL 33142

Date: 05/15/07  
P.O.#: 49034  
Job #: F3067

Grade and Description: 4140 Block

Specification: ASTM A669 Class J Rev 04  
Drawing #: 15-1/4" x 8-3/4" x 60" LG.

Job #	Piece #	Heat/ Ingot #	Ingot Size	Ingot Weight	Product Size	Shipped Weight
F3067	09	R8242-2			8-3/4 X 15-1/4 X 60-1/4	
	10	R8242-2			8-3/4 X 15-1/4 X 190-1/8	

CHEMICAL ANALYSIS

Heat #	C	Mn	P	S	Si	Ni	Cr	Mo	Al	V	Cu	Hppm	Tl
R8242	.43	.89	.015	.025	.22	.12	.99	.22	.019	.050	.17	1.3	.0032

TENSILE TEST RESULTS: TENSILE TEST DIA. .505"

BRINELL RESULTS

TENSILE TESTS TAKEN FROM PC 08

Piece #	Test Loc	Yield Strength % offset	Tensile Strength	Elong in 2"	RA %	BRINELL
08		84,573	113,196	18	49	236-240-244-245
		83,946	110,613	19	49	

IMPACT RESULTS: TEST SIZE: 10mm x 10mm

Piece#	Test Loc	Test Temp	Ft lbs.	%Shear	Lateral Expansion
--------	----------	-----------	---------	--------	-------------------


HEAT TREATMENT OF PC 08 HEAT TREATED IN FURNACES CERTIFIED TO AMS -H-6875  
HEAT TO 1575 DEG F 4 HRS MIN POLY QUENCH, TEMPER 1225 DEG F 9 HRS  
SONIC TESTED P ASTM A 388 - REVEALED NO INDICATIONS

Signed: \_\_\_\_\_

*Healy Lasele*

Certification Clerk

For particular 4140 forging 



$$CE = C + \frac{(Mn + Si)}{6} + \frac{(Cr + Mo + V)}{5} + \frac{(Ni + Cu)}{15}$$

## **“Tools” that were used:**

- A large scale mock up
- Procedure qualification
- Preheat
- Interpass temperature
- Postheat
- Stress Relief
- Buttering
- DC- buttering procedures
- Decarburizing flux
- E7018 tack welding
- Careful supervision
- A fabricator willing to do whatever was best for the project
- A cooperative Owner

**SAW**

Welding Procedure Specification

JOB SPECIFIC ( 5252 )

Material Spec. ASTM A668 CLASS J FORGING

Welding Process(es) SAW

Position of Welding FLAT ( CLADDING )

Manual  Machine  Semi-Automatic  Automatic

Filler Metal Specification 5.17

Filler Metal Classification EM12K LINCOLN L-61

Flux F7A2 LINCOLN 860

Gas Flow Rate N/A

**Cladding  
("buttering")**

**L61/860**

**DCEN: direct current,  
electrode negative**

**Preheat: 450°F  
Max. Interpass: 650°F**

Welding Current DC

Polarity: AC  DCEP  **DCEN**  Pulsed

Welding Progression Up  Down

Root Treatment N/A

Preheat Temperature 450 DEGREES (F)

Interpass Temperature 650 DEGREES (F)

Postheat Treatment N/A

Heat Input Min 37

Max 59.4



PIPE +  
DIES  
ONLY

LOCKER

07/10/2007




07/10/2007



ARC WELDER

LOCKER  
PIPE +  
DIES

07/10/2007




REDUCED SECTION TENSION SPECIMEN FROM MOCK-UP

(2) REQUIRED



08/23/2007









09/27/2007



1

2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

1 2 3 4 5 6 7 8 9 10

11 12 13 14 15 16 17 18 19 20 21 22 23

24

25

26

27

28

29

30

31

32

33

34

35

36

37





# 2020 Mid-Atlantic Quality Assurance Workshop



## Causes and Prevention of Weld Cracking

by

Duane K. Miller, P.E., Sc.D

