



### **S.R. 376 West Mainline Truck Detour Section A**

1. From SR 376 WB, take exit 72B SR 376 WB off Ramp to Blvd. of Allies/Liberty Bridge
2. Take the Liberty Bridge, and continue through Liberty Tunnel.
3. Turn right out of tunnel onto PA 51 North / Truck US 19 / West End.
4. Take Exit to West I-376 / South US 19 toward Carnegie / Airport / West End.
5. Take Exit 69A toward South US 19/ Banksville Road.
6. Keep right toward I-376 Westbound Airport or Keep left and loop back to I-376 Eastbound toward Ft Pitt Tunnel.