

EXISTING ROADWAY CONDITIONS

GRADES ARE SEVERE:

- SR 2019 (Grayson Road) 9.7% (Design Criteria Recommended Maximum is 8%)
- □ SR 2019 (Milroy Road) 13.7% (Recommended Maximum is 8%)
- □ SR 3006 (Chambers Hill Road) 10.7% (Recommended Maximum is 9%)

ANGLE OF APPROACH ROADS ARE SEVERE:

- □ Design Criteria Greater than 60° is Desired
 - SR 2019 (Grayson Road) 10°
 - Hilton Street 10°
 - SR 3006 (Chambers Hill Road) 30°
 - 82nd Street 60°

PAXTON STREET PAXTON STREET SOO ROAD PAXTON STREET SOO ROAD FOR STREET F

POOR CAPACITY

- Main Intersection (existing)
 - Level of Service (LOS) = F (the worst grade)
 - +100 seconds per vehicle delay (both in the AM and PM peak periods)
 - Gets worse over time
- Grayson Road and Milroy Road Intersection is "Gridlocked" at times
 - LOS F in the PM



