

## The GUIDE-ing LITE Fox Township, Elk County

### Problem/Challenge Addressed

We have issues with buildup of anti-skid and leaves under guide rails preventing stormwater from properly draining. This causes ponding in flat areas of the road and washouts of the shoulder on hills. Cleaning under guide rails is a very labor-intensive task.

### Method/Process/Product to Resolve Challenge

We needed an inexpensive solution that will also save us time, so using our skid-steer, we built a pusher to fit on the forks and used some chains to hold it in place. The total cost for this project was only \$239.



### Results/Key Takeaways

A task that used to take five people and a backhoe all day can now be done with the same five people but in only two hours. Plus, this reduces chances of injury.



### Contact Information

Name: Randy Gradizzi  
Phone Number: 814-885-8450 ext. 1  
Email Address: rgradizzi-foxtwp@ncentral.com