



**SR 19 / 51 (Saw Mill Run Blvd.) Southbound Detour for Shaler St. Bridge Replacement**

1. From the West End Circle, take Steuben Street
2. Turn left onto Short Street
3. Bear right onto South Main Street
4. Turn left onto Wabash Street
5. Wabash Street becomes Greentree Road
6. Turn left onto Woodville Avenue
7. Turn right onto the ramp to I-376 Parkway West
8. To continue to southbound Route 19, bear left toward South Truck 19/51 toward Uniontown
9. Stay left toward East 376/South 51 toward Uniontown
10. Take the South Truck 19/51 ramp (Exit 69B) toward Uniontown

Detour Route
  CLOSED Route
  Construction Area