



Milling of existing bituminous pavement



Rockfall fence at northern cut



Bituminous paving at northern cut



Bituminous paving at southern cut



Restoration work completed on existing stone wall



Southern cut area just prior to opening



Northern cut area just prior to opening