



Liberty Bridge Detour Consol Energy Alternate Routes Outbound

Route for Vehicles Exiting Consol Energy Center Parking Lots on Bedford Avenue:

1. Take Ramp to I-376 West, 7th Avenue and Ft Pitt Bridge to 7th Avenue.
2. Turn Right onto Grant Street.
3. Turn Left onto 11th Street.
4. Stay Straight onto 10th Street Bypass.
5. Take and follow Exit to I-376 West, Ft Pitt Bridge, and Airport.

Route for Vehicles Exiting Consol Energy Center Lots onto 6th Avenue:

1. Follow Centre Avenue then turn Right onto 6th Avenue.
2. Turn Left onto Grant Street.
3. Follow Grant Street Southbound to the West I-376 Access Ramp near the Ft Pitt Boulevard / Grant Street Intesection.
4. Follow I-376 West, Ft Pitt Bridge, and Airport.

Once both Outbound Consol Energy Alternate Routes are following I-376 West:

6. Follow I-376 Westbound across Ft Pitt Bridge and through the Ft Pitt Tunnel.
7. Take Exit 69A toward South US 19 / Banksville Road.
8. Keep Left and loop back to I-376 Eastbound toward South Truck US 19 / South SR 51.
9. Follow I-376 Eastbound and take Exit 69B toward South Tuck US 19/ to South SR 51. Merge onto and follow South SR 51.
10. Follow SR 51 to the SR 51 / US 19 / West Liberty Avenue Interchange.