



Walmart

Lack of formal right turn lane leads drivers to use shoulder

High number of reported injury crashes due to frequent angle collisions

Missing sidewalk connection under SR 222 bridges

Northbound SR 222 On-Ramp

Turkey Hill

Bergstrasse Evangelical Lutheran Church

Arby's

322

Sunoco

Frequent traffic back-ups approaching signal

Sheetz

Urgent Care

Southbound SR 222 On-Ramp

Lack of signal control leads to unprotected left turn movement

Existing bridge clearances do not meet current standards

Short left turn lanes cause traffic to routinely back-up into SR 322 travel lanes

Northbound SR 222 Off-Ramp

Lack of formal right turn lane leads drivers to use shoulder

Traffic back-ups along ramp during peak periods

322

